


Good day,

I am trying to use the fdc2114 to measure humidity. This is the current schematic.



This is my first time working with i2c or the fdc2114. Does someone see a mistake in the schematic or config?

Regards

Simon